

Oil Field Environmental Incident Summary

Incident: 20140127100816 **Date/Time of Notice:** 01/27/2014 10:03

Responsible Party: Kodiak Oil & Gas

Well Operator: KODIAK OIL & GAS (USA) INC.

Well Name: BORRUD 156-101-1-12-1H

Field Name: TYRONE

Well File #: 22495

Date Incident: 1/24/2014

Time Incident: 1215

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 101

Sec: 1

Qtr:

Location Description:

Submitted By: Britiny Fabry

Received By:

Contact Person: Chuck Zinne
1625 BROADWAY STE 250
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: 1 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	280	barrels	280	barrels	260	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/26/2016

Clean Up Concluded: 1/27/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

contaminated gravel

Action Taken or Planned:

Sucked up water and hauled to disposal. Cleaned up gravel and replacing it with new. Pipe support needs to be installed under lines

Wastes Disposal Location: An approved disposal site

Agencies Involved:

Updates

Date: 1/27/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a piping leak, remained on location, according to the report. However, due to size of release, please visit and confirm that it remained on location, and in the oversight of NDIC.

Date: 1/28/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:00 1/28/14.

Impacted area has been scraped up, with new gravel brought into the location. Equipment has been upgraded.

No followup necessary.